

**ENVIRONMENTAL REPORT**

**TO: Rory O'Callaghan, SEE Environment**

**FROM: Ann Marie Callan, Executive Scientist**

**RE: Water Quality Monitoring at New 400/110KV Substation at Coolnabacky.**

**Date: 22 March 2022**

On 22/03/2022, I carried out an inspection of the Substation site at Coolnabacky and noted the following:

1. No operations or activities on site
2. Satisfactory Sediment curtains remain in place.
3. Noted satisfactory storage of excavated soils on site
4. No unauthorized discharges to surface waters noted.
5. All watercourses on and adjacent the site was noted to be of good quality with no evidence of unauthorized discharges/contamination that would give rise to a deterioration in water quality.

See photographs attached.

Signed:   
Ann Marie Callan

Date: 23/3/22





Photographs taken at Substation at Coalnascety on  
22/3/22 by Ann Marie Callan















