

ENVIRONMENTAL REPORT

TO: Rory O'Callaghan, SEE Environment

FROM: Ann Marie Callan, Executive Scientist

RE: Water Quality Monitoring at New 400/110KV Substation at Coolnabacky.

Date: 27 April 2022

On 27/04/2022, I carried out an inspection of the Substation site at Coolnabacky and noted the following:

1. Road construction operations on site
2. Satisfactory Sediment curtains remain in place.
3. Noted satisfactory storage of excavated soils on site
4. No unauthorised discharges to surface waters noted.
5. All watercourses on and adjacent the site was noted to be of good quality with no evidence of unauthorised discharges/contamination that would give rise to a deterioration in water quality.

See photographs attached.

Signed: 

Ann Marie Callan

Date: 27/4/22

Photographs taken by Ann Marie Callan on 27/4/22
at 400/100KV Substation at Coolnabacky.



Photo 1: Stockpile of excavated soil



Photo 2: New Road Works




Photo 3: Landdrawn adjacent new road



Photo 5:



Photo 4:



Photo 7



Photo 6



Photo 8: Watercourse at site.



Photo 9: Watercourse on site.

