

Title:

OHT1 Pack
N1021058

Title:

OHT1 Pack
N1021058

OHT1 Application

Barcode: N1021058

Road Name: GARRANBAUN, CAMROSS, STOUGH

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.688622, 52.998782

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 3.1 Can shielding by re-directional


Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

Location on the outside of a curve: No

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





T: 0818 624 624

W: www.nbi.ie

E: contactus@nbi.ie

Citywest

Dublin 24

D24 H6RR

Title:

CHT1 Pack
N1021135

Legend:

OHT1 Application

Barcode: N1021135

Road Name: MOUNTOLIVER, ERRILL

Road Segment: Surface: Grass Ribbon: B

Coordinates: -7.633028, 52.862172

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 2.5 Can shielding by re-dire

Can shielding by re-directional feature or existing hazard?: No Does the pole need a stay: No


Municipal District: Borris in Ossory Mountmellick



Location on the outside of a curve: No

Location within 10m of a junction: No

Location on a downgrade 5%: Yes Is the pole location acceptable: Yes



Road Name: STOUGH, NEALSTOWN, ROSCREA

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.691357, 52.998402

Existing Pole Line: No Collision Record: No **Driving Speed:** 43 Measured Offset: 4

Can shielding by re-directional

Municipal District: Borris in Ossory Mountmellick

Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes feature or existing hazard?: No Does the pole need a stay: No

Location on the outside of a curve: No







Road Name: GARRANBAUN, CAMROSS

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.683061, 52.999275

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 3.3 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: Yes Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





OHT1 Pack N1021225

Title:





Road Name: BALLINLA, BORRIS-IN-OSSORY

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.692744, 52.962049

Existing Pole Line: No Collision Record: No **Driving Speed:** 64 Measured Offset: 3.5 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick









Road Name: GARRANBAUN, CAMROSS

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.687687, 52.998816

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 4.2 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





OHT1 Pack N1021362

OHT1 Application

Legend:



T: 0818 624 624
E: contactus@nbi.ie
W: www.nbi.ie

Title:

OHT1 Pack
N1021400

OHT1 Application

Barcode: N1021400

Road Name: MOUNTOLIVER, ERRILL

Road Segment: Surface: Grass Ribbon: B

Coordinates: -7.634169, 52.862426

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 2.7 Can shielding by ro dire

Can shielding by re-directional feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick



Location on the outside of a curve: No

Location within 10m of a junction: No

Location on a downgrade 5%: No

Is the pole location acceptable: Yes



Title:

Citywest

Dublin 24

D24 H6RR


T: 0818 624 624

W: www.nbi.ie

E: contactus@nbi.ie

OHT1 Pack

N1021428



Barcode: N1021428

Road Name: GARRANBAUN, CAMROSS

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.68955, 52.998703

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 4.1


Can shielding by re-directional feature or existing hazard?: No

Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes





Title:

CHT1 Pack
N1021478

OHT1 Application

OHT1 Application

T: 0818 624 624

W: www.nbi.ie

E: contactus@nbi.ie

Barcode: N1021478

Road Name: STOUGH, NEALSTOWN, ROSCREA

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.690464, 52.998575

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 4.5 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





Road Name: CLONCULLY, BORRIS-IN-OSSORY

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.640745, 52.97937

Existing Pole Line: No Collision Record: No Driving Speed: 66 Measured Offset: 3.5 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





OHT1 Pack N1021490

Title:

Legend:

OHT1 Application



Road Name: GARRANBAUN, CAMROSS

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.692251, 52.998228

Existing Pole Line: No Collision Record: No Driving Speed: 43 Measured Offset: 3.8 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





OHT1 Pack N1021525

Title:

Legend:

OHT1 Application



Road Name: BALLINLA, BORRIS-IN-OSSORY

Road Segment: Surface: Grass Ribbon: A

Coordinates: -7.69325, 52.961722

Existing Pole Line: No Collision Record: No **Driving Speed:** 64 Measured Offset: 3.5 Can shielding by re-directional

Location on the outside of a curve: No Location within 10m of a junction: No Location on a downgrade 5%: No Is the pole location acceptable: Yes

feature or existing hazard?: No Does the pole need a stay: No

Municipal District: Borris in Ossory Mountmellick





OHT1 Pack N1021704

Title:

Legend: **OHT1** Application